

Please email your written response to [safety@dopl.idaho.gov](mailto:safety@dopl.idaho.gov). Please include your Facility/Business No on the reply.

Office: 208-334-3233  
E-mail: [safety@dopl.idaho.gov](mailto:safety@dopl.idaho.gov)

---

## FACILITY REPORT

Facility / Business No: E-411-0003 / 9030

Inspector: JEFF HARRIS

Inspection Date: 04/07/2021

Owner: Twin Falls School Dist #411

201 Main Ave West

Twin Falls, ID 83301

Location:

Twin Falls Sr High School

1615 FILER AVE E

TWIN FALLS, ID 83301

Contact: Emory Warren

Contact Phone: 2087334277

Contact E-mail: [warrenem@tfsd.org](mailto:warrenem@tfsd.org)

---

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

---

### Recommendations:

(4/14/2021 8:43 AM JHA)

1. 3rd. REPEAT: 1910.36(g)(4) Objects that project into the exit route must not reduce the width of the exit route to less than the minimum width requirements for exit routes

Desks in room # D-9 obstructing egress.

2. 1910.159(c)(2) The employer shall properly maintain an automatic sprinkler system installed.

Recommend protective cages over sprinklers in walkins.

Please email your written response to [safety@dopl.idaho.gov](mailto:safety@dopl.idaho.gov). Please include your Facility/Business No on the reply.

Office: 208-334-3233  
E-mail: [safety@dopl.idaho.gov](mailto:safety@dopl.idaho.gov)

---

## FACILITY REPORT

Facility / Business No: E-411-0003 / 9030

Inspector: JEFF HARRIS

Inspection Date: 02/28/2022

Owner: Twin Falls School Dist #411  
201 Main Ave West  
Twin Falls, ID 83301

Location:  
Twin Falls Sr High School  
1615 FILER AVE E  
TWIN FALLS, ID 83301

Contact: Emory Warren  
Contact Phone: 2087334277  
Contact E-mail: [warrenem@tfsd.org](mailto:warrenem@tfsd.org)

---

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

---

### Recommendations:

(3/8/2022 1:40 PM JHA)

1. 1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels.

electrical panels in Weights are obstructed.

2. IFC 605.3.1 Labeling: Doors into electrical control panel rooms shall be marked with a plainly visible and legible sign stating ELECTRICAL ROOM or similar approved wording. The disconnecting means for each service, feeder or branch circuit originating on a switchboard or panelboard shall be legibly and durably marked to indicate its purpose unless such purpose is clearly evident

Recommend labeling unidentified rooms with electrical panels.

3. 1910.37(a)(3) Exit routes must be free and unobstructed. No materials or equipment may be placed, either permanently or temporarily, within the exit route. The exit access must not go through a room that can be locked, such as a bathroom, to reach an exit or exit discharge, nor may it lead into a dead-end corridor. Stairs or a ramp must be provided where the exit route is not substantially level.

4. General Duty Clause: 5. Duties (a) Each employer (1) shall furnish each of his employees employment and a place of employment which are free from recognized hazards that are causing or are likely to cause death or serious physical harm to his employees.

Multiple doors shut way too fast.

5. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows.

Recommend Housekeeping in Robotics.

Please email your written response to [safety@dopl.idaho.gov](mailto:safety@dopl.idaho.gov). Please include your Facility/Business No on the reply.

Office: 208-334-3233  
E-mail: [safety@dopl.idaho.gov](mailto:safety@dopl.idaho.gov)

## FACILITY REPORT

Facility / Business No: **E-411-0003 / 9030**

Inspector: JEFF HARRIS

Inspection Date: 03/27/2023

Owner: Twin Falls School Dist #411

201 Main Ave West

Twin Falls, ID 83301

Location:

Twin Falls Sr High School

1615 FILER AVE E

TWIN FALLS, ID 83301

Contact: Emory Warren

Contact Phone: 2087334277

Contact E-mail: [warrenem@tfsd.org](mailto:warrenem@tfsd.org)

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

### Recommendations:

(4/12/2023 9:25 AM JHA)

1. 1910.176(b) Storage of material shall not create a hazard. Bags, containers, bundles, etc., stored in tiers shall be stacked, blocked, interlocked and limited in height so that they are stable and secure against sliding or collapse.

Recommend securing tall shelf in Main office & Staff lounge.

2. 1910.305(b)(3)(i) Boxes shall provide a complete enclosure for the contained conductors or cables.

Receptical in security room needs cover plate.

3. (150.06.a) Electric power taps shall be plugged directly to an approved electric receptacle. They shall not be "daisy chained", "piggy backed" or otherwise connected to one another.

Piggybacked power strip in B-5, & G-04.

4. 1910.37(a)(1) Exit routes must be kept free of explosive or highly flammable furnishings or other decorations.

General note throughout facility not to decorate classroom egress doors.

5. IFC 807.4.3.2 Artwork. Artwork and teaching materials shall be limited on the walls of corridors to not more than 20 percent of the wall area. And 50% of protected class rooms.

Room # D-9 appears to exceed the recommended limits.

6. (150.06.b) There is a multi plug adapter in use.

Room # D-6 has a multi port adaptor .

7. 1910.159(c)(10) The minimum vertical clearance between sprinklers and material below shall be 18 inches.

D-5, Jive storage, & Instrument storage.

8. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows.

Recommend Housekeeping in Choir office , & D-5.

9. 1910.242(a) Each employer shall be responsible for the safe condition of tools and equipment used by employees, including tools and equipment which may be furnished by employees.

Doors in C-1, & Art storage close way too fast.

10. 1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels.

Panel in Athletic Medicine is obstructed.