

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0010 / 6075

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High Sch. Trailer #1

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/13/2020 8:56 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES WERE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition.

1910.22(b) The employer must ensure that each walking-working surface can support the maximum intended load for that surface. Steps and ramp. MULTI YEAR REPEAT

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0010 / 6075

Inspector: RUSSELL SIDELL

Inspection Date: 11/17/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High Sch. Trailer #1

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/18/2021 1:51 PM RSI)

1. For the past several years D.B.S. has noted the egress stairs and ramp are un-safe. Staff noted all materials have been removed from trailer, power and heat turned off. D.B.S. inspector did not enter facility. District plans to remove from property.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0010 / 6075

Inspector: RUSSELL SIDELL

Inspection Date: 11/29/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High Sch. Trailer #1

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/30/2022 5:52 AM RSI)

1. Staff noted the facility is no longer used. The stairs and ramp are unsafe and have been listed for a number of years as a unsafe condition. District plans are to removed facility there is no power or water. (Exterior only)

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0011 / 6076

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg A

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/16/2020 6:20 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES WERE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels. IFC 315.3.3 Equipment rooms. Combustible material shall not be stored in boiler rooms, mechanical rooms or electrical equipment rooms. Facility electrical rooms are being used as storage areas.

2. 1910.37(d)(2) During repairs or alterations, employees must not occupy a workplace unless the exit routes required by this subpart are available and existing fire protections are maintained, or until alternate fire protection is furnished that provides an equivalent level of safety. I.T. room ceiling tiles have been removed REPEAT. Library ceiling tiles have been removed.

3. 1910.36(g)(2) An exit access must be at least 28 inches wide at all points. Where there is only one exit access leading to an exit or exit discharge, the width of the exit and exit discharge must be at least equal to the width of the exit access.

1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows.

1910.176(c) Storage areas shall be kept free from accumulation of materials that constitute hazards from tripping, fire, explosion, or pest harborage. Vegetation control will be exercised when necessary. Practice Gym storage rooms.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0011 / 6076

Inspector: RUSSELL SIDELL

Inspection Date: 11/16/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg A

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/18/2021 12:25 PM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels. REPEAT
IFC 605.3.1 Labeling: Doors into electrical control panel rooms shall be marked with a plainly visible and legible sign stating ELECTRICAL ROOM or similar approved wording. The disconnecting means for each service, feeder or branch circuit originating on a switchboard or panelboard shall be legibly and durably marked to indicate its purpose unless such purpose is clearly evident
IFC 315.3.3 Equipment rooms. Combustible material shall not be stored in boiler rooms, mechanical rooms or electrical equipment rooms.
Facility electrical rooms. REPEAT.
2. (information) There is a roof leak in the Gym North wall. Damaging the wood floor.
3. 1910.212(a)(3) Point of operation guarding. - Paper cutters are required to have a guard parallel to the cutting blade. Main office workroom.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0011 / 6076

Inspector: RUSSELL SIDELL

Inspection Date: 11/28/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg A

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/29/2022 6:36 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. NO UNSAFE OR HAZARDOUS CONDITIONS NOTED ON THIS DATE

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0013 / 6077

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg B

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/16/2020 6:27 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES WERE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.151(c) Where the eyes or body of any person may be exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body shall be provided within the work area for immediate emergency use. 2nd level custodial closet eye wash has been removed. 5th year REPEAT.

2. 1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels. B-74.

3. (150.06.a) Electric power taps shall be plugged directly to an approved electric receptacle. They shall not be "daisy chained", "piggy backed" or otherwise connected to one another.

(150.05.k) Flexible electric extension cords are required to be plugged directly to an approved electric receptacle.

1910.305(g)(1)(iii) The flexible cord shall be equipped with an attachment plug and shall be energized from an approved receptacle outlet.

Room # B-17 using piggy back method of extending outlets. X7

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0013 / 6077

Inspector: RUSSELL SIDELL

Inspection Date: 11/17/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg B

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/18/2021 1:46 PM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.305(g)(1)(iv)(A) There is an ungrounded light duty extension cord in use as a substitute for the fixed wiring of a structure. Household listed extension cord in use. Room # B-19.

2. 

3. On the day of inspection D.B.S. did not enter several classrooms. (Finals)

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0013 / 6077

Inspector: RUSSELL SIDELL

Inspection Date: 11/28/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg B

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us


A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/29/2022 6:50 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 
2. 1910.305(g)(1)(iii) The flexible cord shall be equipped with an attachment plug and shall be energized from an approved receptacle outlet. on the day of inspection a large number of rooms were using the piggy back method of extending outlets.
3. 1910.305(g)(1)(iv)(A) There is an ungrounded light duty extension cord in use as a substitute for the fixed wiring of a structure. (Household rated two wire) Room # B-3 and Room # B-19 is a REPEAT.
4. 1910.36(g)(4) Objects that project into the exit route must not reduce the width of the exit route to less than the minimum width requirements for exit routes Need to monitor classroom configuration.
5. 1910.159(c)(2) The employer shall properly maintain an automatic sprinkler system installed. Room # 1 hanging paper on sprinkler line.
6. 1910.37(d)(2) During repairs or alterations, employees must not occupy a workplace unless the exit routes required by this subpart are available and existing fire protections are maintained, or until alternate fire protection is furnished that provides an equivalent level of safety. The book storage room next to B-16. (Missing ceiling tiles water leaks?).

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0015 / 6079

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg D

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/16/2020 6:46 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES WERE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. (030.07.a) Materials are required to be properly stacked.

1910.176(b) Storage of material shall not create a hazard. Bags, containers, bundles, etc., stored in tiers shall be stacked, blocked, interlocked and limited in height so that they are stable and secure against sliding or collapse. Choir room.

2. 1910.37(b)(6) Each exit sign must be illuminated to a surface value of at least five foot-candles (54 lux) by a reliable light source and be distinctive in color. Self-luminous or electroluminescent signs that have a minimum luminance surface value of at least .06 footlamberts are permitted. Several exit signs are out of date. (Tritium).

3. IFC 313.1 General. Fueled equipment including, but not limited to, motorcycles, mopeds, lawn-care equipment, portable generators and portable cooking equipment, shall not be stored, operated or repaired within a building. Band room. (storing gas powered generator in South egress area.

4. 1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels.

IFC 315.3.3 Equipment rooms. Combustible material shall not be stored in boiler rooms, mechanical rooms or electrical equipment rooms.

5. 1910.37(a)(3) Exit routes must be free and unobstructed. No materials or equipment may be placed, either permanently or temporarily, within the exit route. The exit access must not go through a room that can be locked, such as a bathroom, to reach an exit or exit discharge, nor may it lead into a dead-end corridor. Stairs or a ramp must be provided where the exit route is not substantially level. Choir room hallway is being used to store materials. REPEAT.

6. IFC 807.1 General requirements. In occupancies in Groups A, E, I and R-1, and dormitories in Group R-2, curtains, draperies, hangings and other decorative materials suspended from walls or ceilings shall meet the flame propagation performance criteria of NFPA 701 in accordance with Section 807.2 or be noncombustible. Stage curtains REPEAT.

7. (Information) Weight room benches. Recommend following industry standards. Repair or replace. REPEAT.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0015 / 6079

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg D

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

8. 1910.176(c) Storage areas shall be kept free from accumulation of materials that constitute hazards from tripping, fire, explosion, or pest harborage. Vegetation control will be exercised when necessary. A number of facility storage rooms need to be cleaned and organized including cheerleader closets.

9. 1910.305(g)(1)(iii) The flexible cord shall be equipped with an attachment plug and shall be energized from an approved receptacle outlet. Wrestling room. Piggy backing.

10. 1910.252(c)(2)(i)(C) Mechanical ventilation shall be provided when: In confined spaces or where the welding space contains partitions, balconies, or other structural barriers to the extent that they significantly obstruct cross ventilation. It does not appear that the current exhaust system in welding room is designed for the amount of welding being done. 6th year REPEAT.

11.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0015 / 6079

Inspector: RUSSELL SIDELL

Inspection Date: 11/16/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg D

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/18/2021 1:36 PM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. Combustible storage is not allowed under unprotected exit stairways.

IFC 315.3.4 Attic, under-floor and concealed spaces. Attic, under-floor and concealed spaces used for storage of combustible materials shall be protected on the storage side as required for 1-hour fire-resistance-rated construction.

Baseball lab (Wood, upholstered furniture)

2. 1910.176(b) Storage of material shall not create a hazard. Bags, containers, bundles, etc., stored in tiers shall be stacked, blocked, interlocked and limited in height so that they are stable and secure against sliding or collapse.

Stage storage on top of ceiling-roof. (Not a rated or protected storage area.)

Choir room REPEAT.

3. 1910.37(b)(6) Each exit sign must be illuminated to a surface value of at least five foot-candles (54 lux) by a reliable light source and be distinctive in color. Self-luminous or electroluminescent signs that have a minimum luminance surface value of at least .06 foot lamberts are permitted. Several tritium exit signs are out of date.

REPEAT.

4. IFC 313.1 General. Fueled equipment including, but not limited to, motorcycles, mopeds, lawn-care equipment, portable generators and portable cooking equipment, shall not be stored,

operated or repaired within a building. Band room South exit (Storing gas powered generator in exit vestibule)

REPEAT FULL OF FUEL!!

5. IFC 315.3.3 Equipment rooms. Combustible material shall not be stored in boiler rooms, mechanical rooms or electrical equipment rooms.

1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels. REPEAT.

IFC 605.3.1 Labeling: Doors into electrical control panel rooms shall be marked with a plainly visible and legible sign stating ELECTRICAL ROOM or similar approved wording. The disconnecting means for each service, feeder or branch circuit originating on a switchboard or panelboard shall be legibly and durably marked to indicate its purpose unless such purpose is clearly evident

HIGHLY ECOMMEND NO STORAGE SIGNS.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0015 / 6079

Inspector: RUSSELL SIDELL

Inspection Date: 11/16/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg D

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

6. IFC 807.1 General requirements. In occupancies in Groups A, E, I and R-1, and dormitories in Group R-2, curtains, draperies, hangings and other decorative materials suspended from walls or ceilings shall meet the flame propagation performance criteria of NFPA 701 in accordance with Section 807.2 or be noncombustible. Stage curtains. MULTI YEAR REPEAT.

7. (Information) Weight room benches, Need to maintain ability to properly clean. (Industry standards).

8. 1910.303(b)(2) Listed or labeled equipment shall be installed and used in accordance with any instructions included in the listing or labeling. Wrestling room. Hanging materials on ceiling mounted natural gas lines and electrical conduit.

9. 1910.252(c)(2)(i)(C) Mechanical ventilation shall be provided when: In confined spaces or where the welding space contains partitions, balconies, or other structural barriers to the extent that they significantly obstruct cross ventilation. It does not appear that the current shop ventilation is designed for the number and type of welding being done. 7th year REPEAT.

10. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows. 1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition. (Trip hazards)
Cheerleader rooms, Wrestling room and storage rooms.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0015 / 6079

Inspector: RUSSELL SIDELL

Inspection Date: 11/28/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg D

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/29/2022 7:13 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.151(c) Where the eyes or body of any person may be exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body shall be provided within the work area for immediate emergency use. D-Hall custodial closet requires eye wash station. D-hall custodial next to chair room needs to be repaired.
2. 1910.37(b)(6) Each exit sign must be illuminated to a surface value of at least five foot-candles (54 lux) by a reliable light source and be distinctive in color. Self-luminous or electroluminescent signs that have a minimum luminance surface value of at least .06 footlamberts are permitted. Out of date tritium signs REPEAT.
3. IFC 315.3.3 Equipment rooms. Combustible material shall not be stored in boiler rooms, mechanical rooms or electrical equipment rooms.
Highly recommend signs on electrical rooms (No storage) REPEAT.
4. 1910.176(b) Storage of material shall not create a hazard. Bags, containers, bundles, etc., stored in tiers shall be stacked, blocked, interlocked and limited in height so that they are stable and secure against sliding or collapse. Stage, choir room, band room.
5. IFC 807.1 General requirements. In occupancies in Groups A, E, I and R-1, and dormitories in Group R-2, curtains, draperies, hangings and other decorative materials suspended from walls or ceilings shall meet the flame propagation performance criteria of NFPA 701 in accordance with Section 807.2 or be noncombustible. MULTI YEAR REPEAT.
6. (Information) The weight room benches need to be repaired or replaced. (Industry standards) REPEAT.
7. 1910.37(a)(3) Exit routes must be free and unobstructed. No materials or equipment may be placed, either permanently or temporarily, within the exit route. Main Gym storing in front of listed exit.
8. 1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition.
1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows. Cheerleader rooms, Wrestling room and storage. REPEAT And The racquet ball court and chair room. Need to be cleaned and organized.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0015 / 6079

Inspector: RUSSELL SIDELL

Inspection Date: 11/28/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg D

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0017 / 6081

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg C

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/16/2020 6:55 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES WERE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.151(c) Where the eyes or body of any person may be exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body shall be provided within the work area for immediate emergency use.

ANSI Z358.1-Facilities for quick drenching or flushing shall meet the requirements of ANSI Standard Z358.1. and the first aid requirements of the chemicals or materials being used.: Eye wash spray heads and/or quick drench hose are missing protective cover & are not protected from airborne contaminants. Room # C-32 eye wash station is non-operational.

2. 1910.305(g)(1)(iii) The flexible cord shall be equipped with an attachment plug and shall be energized from an approved receptacle outlet. Room # C-41 piggy backing.

3. 1910.37(d)(2) During repairs or alterations, employees must not occupy a workplace unless the exit routes required by this subpart are available and existing fire protections are maintained, or until alternate fire protection is furnished that provides an equivalent level of safety. Room # C-43 I.T. closet the ceiling tiles have been removed. This is a protected facility. 6th year REPEAT.

4. 1910.151(b) In the absence of an infirmary, clinic, or hospital in near proximity to the workplace which is used for the treatment of all injured employees, a person or persons shall be adequately trained to render first aid. Adequate first aid supplies shall be readily available. Out of date first aid supplies. REPEAT.

5. 1910.37(b)(6) Each exit sign must be illuminated to a surface value of at least five foot-candles (54 lux) by a reliable light source and be distinctive in color. Self-luminous or electroluminescent signs that have a minimum luminance surface value of at least .06 footlamberts are permitted. Basement hallway out of date exit signs. (Tritium).

6. 1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels. Electrical room (Varsity).

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0017 / 6081

Inspector: RUSSELL SIDELL

Inspection Date: 11/16/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg C

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us


A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/18/2021 1:10 PM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 
2. 1910.37(a)(3) Exit routes must be free and unobstructed. No materials or equipment may be placed, either permanently or temporarily, within the exit route. Room # C-27 blocking second exit (Furniture).
3. 1910.308(b)(2) Emergency illumination shall include all required means of egress lighting, illuminated exit signs, and all other lights necessary to provide illumination. Where emergency lighting is necessary, the system shall be so arranged that the failure of any individual lighting element, such as the burning out of a light bulb, cannot leave any space in total darkness. C-Hall emergency lighting is non-operational.
4. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows. 1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition.
Riser room access thru storage room. Need to clean and organize (trip hazards).
5. 1910.303(b)(2) Listed or labeled equipment shall be installed and used in accordance with any instructions included in the listing or labeling: multi-plug adapter must comply with NFPA 70 and IFC. There is a multi plug adapter in use. Room # C-40.
6. 1910.212(a)(3) Point of operation guarding. - Paper cutters are required to have a guard parallel to the cutting blade. Room # C-30.
7. 1910.37(b)(6) Each exit sign must be illuminated to a surface value of at least five foot-candles (54 lux) by a reliable light source and be distinctive in color. Self-luminous or electroluminescent signs that have a minimum luminance surface value of at least .06 foot lamberts are permitted. Basement hallway. Out of date tritium exit signs. REPEAT.
8. 1910.36(g)(4) Objects that project into the exit route must not reduce the width of the exit route to less than the minimum width requirements for exit routes Room # C-26A need to monitor classroom configuration. (Desks and furniture).

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0017 / 6081

Inspector: RUSSELL SIDELL

Inspection Date: 11/16/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg C

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

9. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows.

1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition.

C-33 and C-35 storage room s need to be cleaned and organized, remove trip hazards.

10. 1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels. Room # C-33 storage room.

11. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows.

1910.176(c) Storage areas shall be kept free from accumulation of materials that constitute hazards from tripping, fire, explosion, or pest harborage.

1910.132(a) Protective equipment, including personal protective equipment for eyes, face, head, and extremities, protective clothing, respiratory devices, and protective shields and barriers, shall be provided, used, and maintained in a sanitary and reliable condition wherever it is necessary by reason of hazards of processes or environment, chemical hazards, radiological hazards, or mechanical irritants encountered in a manner capable of causing injury or impairment in the function of any part of the body through absorption, inhalation or physical contact.

On the day of inspection several staff members noted the large number of mice in the building. Staff stated multiple mice are being trapped everyday . (Large number of mouse traps in and around student desks). Need to ensure proper PPEs are used.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0017 / 6081

Inspector: RUSSELL SIDELL

Inspection Date: 11/28/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg C

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/29/2022 6:33 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.37(a)(4) Safeguards designed to protect employees during an emergency (e.g., sprinkler systems, alarm systems, fire doors, exit lighting) must be in proper working order at all times. The fire panel has several trouble lights.

2. [REDACTED]

3. 1910.212(a)(3) Point of operation guarding. - Paper cutters are required to have a guard parallel to the cutting blade. Teacher work room.

4. 1910.151(c) Where the eyes or body of any person may be exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body shall be provided within the work area for immediate emergency use. Room # C-31 need to repair eye wash station.
(Mount is broken)

5. 1910.308(b)(2) Emergency illumination shall include all required means of egress lighting, illuminated exit signs, and all other lights necessary to provide illumination. Where emergency lighting is necessary, the system shall be so arranged that the failure of any individual lighting element, such as the burning out of a light bulb, cannot leave any space in total darkness. A number of hallway emergency lights are non-operational. REPEAT.

6. 1910.37(b)(6) Each exit sign must be illuminated to a surface value of at least five foot-candles (54 lux) by a reliable light source and be distinctive in color. Self-luminous or electroluminescent signs that have a minimum luminance surface value of at least .06 footlamberts are permitted. Out of date tritium exit signs. MULTI YEAR REPEAT.

7. 1910.159(c)(2) The employer shall properly maintain an automatic sprinkler system installed. Access to riser room. (need to clear path) REPEAT.

8. 1910.36(g)(4) Objects that project into the exit route must not reduce the width of the exit route to less than the minimum width requirements for exit routes Room # 30 need to monitor all classrooms. (Excess furniture ? configuration of desks).

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0017 / 6081

Inspector: RUSSELL SIDELL

Inspection Date: 11/28/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg C

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

9. 1910.303(g)(1)(i)(B) The width of working space in front of the electric equipment shall be the width of the equipment or 30 in., whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels. C-hall electrical room and Basement next to room C-44. Room #33 storage room REPEAT.

10. 1910.305(g)(1)(iv)(A) There is an ungrounded light duty extension cord in use as a substitute for the fixed wiring of a structure. Room # C-42 (Household extension cords).

11. 1910.305(g)(1)(iv)(B) Flexible electric cords are not allowed to be run through holes in walls, ceilings, or floors. Room C-43 cord running into the ceiling.

12. 1910.305(g)(1)(iii) The flexible cord shall be equipped with an attachment plug and shall be energized from an approved receptacle outlet. Rooms C-33 and C-28. Piggy backing.

13. 1910.303(b)(2) Listed or labeled equipment shall be installed and used in accordance with any instructions included in the listing or labeling. Room # C-29. On the day of inspection staff noted the outlets in room continue to be overloaded. (Blowing circuits)

14. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows. 1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition. Rooms 33 and 35 store rooms need to be cleaned and organized. REPEAT.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0019 / 6083

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg E

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/16/2020 6:12 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES WERE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. (060.04.b) Need to ensure the decorations on the doors are treated with fire retardant or they need to be removed: Flammable or combustible materials shall not be stored in exit corridors or exit enclosures. 1910.37(a)(1) Exit routes must be kept free of explosive or highly flammable furnishings or other decorations. Covering classroom and egress doors.

2. 1910.151(c) Where the eyes or body of any person may be exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body shall be provided within the work area for immediate emergency use.

ANSI Z358.1-Facilities for quick drenching or flushing shall meet the requirements of ANSI Standard Z358.1. and the first aid requirements of the chemicals or materials being used.: Eye wash spray heads and/or quick drench hose are missing protective cover & are not protected from airborne contaminates.

1910.151(c) Where the eyes or body of any person may be exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body shall be provided within the work area for immediate emergency use.

ANSI Z358.1-Facilities for quick drenching or flushing shall meet the requirements of ANSI Standard Z358.1. and the first aid requirements of the chemicals or materials being used.: Eye wash spray head(s) have residue: Activate eye wash at least weekly North side custodial closet eye wash station has been removed.

3. IFC 315.3.3 Equipment rooms. Combustible material shall not be stored in boiler rooms, mechanical rooms or electrical equipment rooms.

1910.39 Employee emergency plans: 4. "Fire prevention housekeeping." The standard calls for the control of accumulations of flammable and combustible waste materials.

It is the intent of this standard to assure that hazardous accumulations of combustible waste materials are controlled so that a fast developing fire, rapid spread of toxic smoke, or an explosion will not occur. This does not necessarily mean that each room has to be swept each day. Employers and employees should be aware of the hazardous properties of materials in their workplaces, and the degree of hazard each poses. Certainly oil soaked rags have to be treated differently than general paper trash in office areas. However, large accumulations of waste paper or corrugated boxes, etc., can pose a significant fire hazard. Accumulations of materials which can cause large fires or generate dense smoke that are easily ignited or may start from spontaneous combustion, are the types of materials with which this standard is concerned. Such combustible materials may be easily ignited by matches, welder's sparks, cigarettes and similar low level energy ignition sources.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0019 / 6083

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg E

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows.

1910.36(g)(2) An exit access must be at least 28 inches wide at all points. Where there is only one exit access leading to an exit or exit discharge, the width of the exit and exit discharge must be at least equal to the width of the exit access.

Basement electrical room/mechanical room is being used as a storage area.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0019 / 6083

Inspector: RUSSELL SIDELL

Inspection Date: 11/16/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg E

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/18/2021 12:41 PM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.156(d) Portable fire extinguishers and respirators shall be inspected at least monthly. Missing monthly checks on several facility extinguishers.
2. 1910.37(a)(3) Exit routes must be free and unobstructed. No materials or equipment may be placed, either permanently or temporarily, within the exit route. Storage in hallway outside of room E-52 (Furniture?).
3. (Information) On the day of inspection the door leading to the stage basement electrical/mechanical room was open. The access passage under stage area was also open (Broken lock set) dirty food trays garbage in room? Safety /security?
4. IFC 315.3.3 Equipment rooms. Combustible material shall not be stored in boiler rooms, mechanical rooms or electrical equipment rooms.
Basement electrical room under stage MULTI YEAR REPEAT.
5. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows. 1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition.
Room #52, stage area, electrical room under stage.
Areas need to be cleaned and organized, clear walking/egress path.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0019 / 6083

Inspector: RUSSELL SIDELL

Inspection Date: 11/28/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Highland High School Bldg E

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/29/2022 6:12 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition. South exit stairs need to be repaired or replaced. (Trip hazards).
2. [REDACTED]
3. 1910.303(b)(2) Listed or labeled equipment shall be installed and used in accordance with any instructions included in the listing or labeling. Room # E-50 Full size fridge is plugged into a surge protector.
4. 1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition. Stage and room # 52 Trip hazards.
5. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows. 1910.39 Employee emergency plans: 4. "Fire prevention housekeeping." The standard calls for the control of accumulations of flammable and combustible waste materials. The stage need to be cleaned and organized. REPEAT.
6. 1910.176(c) Storage areas shall be kept free from accumulation of materials that constitute hazards from tripping, fire, explosion, or pest harborage. Vegetation control will be exercised when necessary. Basement student government storeroom.
7. 1910.37(a)(3) Exit routes must be free and unobstructed. No materials or equipment may be placed, either permanently or temporarily, within the exit route. Stage East door.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0072 / 6123

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Greenhouse Highland High

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/13/2020 9:08 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES WERE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.151(b) In the absence of an infirmary, clinic, or hospital in near proximity to the workplace which is used for the treatment of all injured employees, a person or persons shall be adequately trained to render first aid. Adequate first aid supplies shall be readily available. First aid kit supplies are out of date.

2. 1910.151(c) Where the eyes or body of any person may be exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body shall be provided within the work area for immediate emergency use.

ANSI Z358.1-Facilities for quick drenching or flushing shall meet the requirements of ANSI Standard Z358.1. and the first aid requirements of the chemicals or materials being used.: Eye wash spray heads and/or quick drench hose are missing protective cover & are not protected from airborne contaminates.

1910.151(c) Where the eyes or body of any person may be exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body shall be provided within the work area for immediate emergency use.

ANSI Z358.1-Facilities for quick drenching or flushing shall meet the requirements of ANSI Standard Z358.1. and the first aid requirements of the chemicals or materials being used.: Eye wash spray head(s) have residue: Activate eye wash at least weekly Facility requires an eye wash station.

(Portable eye wash out of date and non-operational)

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0072 / 6123

Inspector: RUSSELL SIDELL

Inspection Date: 11/17/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Greenhouse Highland High

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/18/2021 1:41 PM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. NO UNSAFE OR HAZARDOUS CONDITIONS NOTED ON THIS DATE

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0072 / 6123

Inspector: RUSSELL SIDELL

Inspection Date: 11/29/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Greenhouse Highland High

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/30/2022 5:45 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. NO UNSAFE OR HAZARDOUS CONDITIONS NOTED ON THIS DATE

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0165 / 6183

Inspector: RUSSELL SIDELL

Inspection Date: 11/12/2020

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Drama Storage

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/13/2020 9:03 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES WERE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows. 1910.176(c) Storage areas shall be kept free from accumulation of materials that constitute hazards from tripping, fire, explosion, or pest harborage. Vegetation control will be exercised when necessary. 1910.39 Employee emergency plans: 4. "Fire prevention housekeeping." The standard calls for the control of accumulations of flammable and combustible waste materials.

It is the intent of this standard to assure that hazardous accumulations of combustible waste materials are controlled so that a fast developing fire, rapid spread of toxic smoke, or an explosion will not occur. This does not necessarily mean that each room has to be swept each day. Employers and employees should be aware of the hazardous properties of materials in their workplaces, and the degree of hazard each poses. Certainly oil soaked rags have to be treated differently than general paper trash in office areas. However, large accumulations of waste paper or corrugated boxes, etc., can pose a significant fire hazard. Accumulations of materials which can cause large fires or generate dense smoke that are easily ignited or may start from spontaneous combustion, are the types of materials with which this standard is concerned. Such combustible materials may be easily ignited by matches, welder's sparks, cigarettes and similar low level energy ignition sources.

1910.36(g)(2) An exit access must be at least 28 inches wide at all points. Where there is only one exit access leading to an exit or exit discharge, the width of the exit and exit discharge must be at least equal to the width of the exit access.

The facility needs to be cleaned and organized.

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0165 / 6183

Inspector: RUSSELL SIDELL

Inspection Date: 11/16/2021

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Drama Storage

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/18/2021 12:30 PM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows.

Housekeeping

1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition. (Trip hazards)

REPEAT

Please email your written response to safety@dopl.idaho.gov. Please include your Facility/Business No on the reply.

Office: 208-334-3233
E-mail: safety@dopl.idaho.gov

FACILITY REPORT

Facility / Business No: E-025-0165 / 6183

Inspector: RUSSELL SIDELL

Inspection Date: 11/29/2022

Owner: Pocatello School District #25

3115 Pole Line Rd

Pocatello, ID 83204

Location:

Drama Storage

1800 BENCH RD

POCATELLO, ID 83201

Contact: Terry Pirrong

Contact Phone: 2082332604

Contact E-mail: pirront1@sd25.us

A response regarding your plans for corrective action for the potential safety hazards is required within 20 calendar days of receipt of report. Corrections need not be completed to respond. Should additional time be needed to formulate responses, an extension of time for up to 60 days may be requested. Include the Business number or State ID number with your response.

Recommendations:

(11/30/2022 5:58 AM RSI)

SAFETY ALERT

EACH YEAR HUNDREDS OF OUR FELLOW EMPLOYEES ARE INJURED ON THE JOB A LARGE PERCENTAGE OF THESE INJURIES WERE DUE TO SLIP AND FALLS THIS INCLUDES SNOW AND ICE, UNEVEN WALKING SURFACES (SIDEWALKS, FLOORS, STEPS), AND HOUSEKEEPING. WE NEED TO KEEP CORDS AND MATERIALS FROM BECOMING TRIP HAZARDS. LETS ALL HELP EACH OTHER GO HOME SAFE EVERY DAY.

1. 1910.141(a)(3)(i) All places of employment shall be kept clean to the extent that the nature of the work allows.
1910.22(d)(1) Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition.

Cannot safely enter facility. (Need to clean and organize, remove trip hazards) MULTI YEAR REPEAT.