



Form: Annual School Inspection 2023

Occupancy: Highland High School

Occupancy ID: 1523 - 27

Address: 1800 Bench RD Pocatello ID 832014999

Inspection Type: Reinspection

Inspection Date: 10/11/2023 By: Wheeler, April A (2305)

Time In: 01:00 Time Out: 03:00

Authorized Date: 10/12/2023 By: Wheeler, April A (2305)

Inspection Description:

Annual Fire Inspection Form 2023

Inspection Topics:

Construction Features

Ceiling tiles in place
Ceiling Tiles in Place
Status: PASS

Notes: corrected on reinspection

No Holes in walls/ceiling

No holes

Status: PASS

Notes: corrected on reinspection. C44 per Terry GFI has been installed on outlet.

Electrical Equipment

No extension cords being used as permanent wiring. Surge protectors are acceptable if UL listed. Cannot be connected together.

No extension cords being used as permanent wiring.

Status: ACTION NEEDED
Notes: AS yet to be addressed:
Office- Kelly's desk surge into surge

B room 2 extension cord running Smart Board TV (has conduit over it.

Electrical panel boxes, receptacles, light switches have proper covers and/or closed

Electrical panel boxes, receptacles, light switches have proper covers and/or closed

Status: ACTION NEEDED **Notes:** As yet to be addressed: B18 outlet is hanging over the TV

Exits & Fire Escapes

Emergency lighting is operable (required if >50)

Emergency lighting is operable (required if >50)

Status: ACTION NEEDED Notes: As yet to be addressed:

In auditorium(left side middle section when facing the stage from a seated position.)

Exit signs illuminated (if more than 1 exit is required)

Exit signs illuminated (if more than 1 exit is required)

Status: ADVISED

Notes: C44 old exit sign need to be replaced

All exit aisles clear from obstructions

All exit aisles clear from obstructions

Status: PASS

Notes: corrected on reinspection

Fire rated, self-closing doors close completely and latch (not propped open)

Fire rated, self-closing doors close completely and latch (not propped open)

Status: PASS

Notes: corrected on reinspection

Housekeeping

Combustibles are not stored in storage room

Combustibles are not stored in storage room

Status: PASS

Notes: corrected on reinspection

No storage or debris in front of exits

No storage in front of exits

Status: ACTION NEEDED

Notes: Drama storage container/shed near E building needs to be orderly as well as exit paths clear .

Stage and Auditorium

Stage exits are clear. Stage area is orderly

Status: ACTION NEEDED

Notes: All stage curtains need to be treated or tested every 5 years per NFPA, must provide verification.

Sprinkler and Standpipe Systems

Escutcheons not missing.

Status: ADVISED

Notes: Inspectors were informed a work order is in place to be completed week of October 16-20.

Rooms A25, C41

Classrooms

Artwork/Decor not excessive (20% of wall space in building w/o sprinkler. 50% in a building with fire sprinklers.

Status: PASS Notes:

Classroom is orderly. (Fire load is not excessive)

Status: ADVISED

Notes: Per International Fire Code, max occupant load is determined by taking the square footage of the classroom and

dividing it by 20. This will give you the total number of occupants allowed in that room at any given time.

Additional Time Spent on Inspection:

Category Start Date / Time End Date / Time

Notes: No Additional time recorded

Total Additional Time: 0 minutes

Inspection Time: 120 minutes

Total Time: 120 minutes

Summary:

Overall Result: Action Needed

Used after initial inspection for inspection deficiencies.

Inspector Notes:

Closing Notes:

Order to Comply: As such conditions are contrary to law, you are hereby required to correct same upon receipt of this notice. An inspection to determine whether you have complied will be conducted on or after the date listed above. Failure to comply with the foregoing order before the date of re-inspection may render you liable to penalties provided by law for such violation (s). Every day that a violation exits may constitute a separate count of the violation(s).